STATINTL STATINTL

on Jan. 27/66. The following Conversation with decisions were arrived at:-

would complete on the processor:

- אשר (1) Slide release consisting of a spring loaded plunger or similar device.
- New (2) A toggle switch on the inspection light. Solution
 - (3) A flow back method between tanks to prevent/carry-over.
- New (4) An anti-splash device on the wash tank.

 -(5) Improve or build air knife.

 - -(6) Complete light baffling
 - (7) Improve the developer tank to accept 9 frames per minute and higher.
- hew -(8) Furnish operational maintenance manuals, including schematics and parts list.
 - (9) Furnish total of 140 slides.
- Juw (10) Take up magazine indicator.

We discussed delivery - as indicated to be the end of February and the only thing that we are leaving out of the specifications as they are written is the dolly replenishment system. I feel that this is a fair trade for the above additional modifications that we have asked for

STATINTL

Delivery point as yet is uncertain and notified as soon as we find out whether it goes to Washington

Declass Review by NIMA/DOD